Yanhua ACDP Automatic Authorization FAQ

Q: After the ACDP bonded, it shows the device does not obtain the authorization of the relevant function, as shown:



Α:

1.Please make sure the IOS version is 1.8.4 or above, and Android version is 3.0.92 or above, as shown:

<	About	۲ About	
Version	Mini ACDP build:71 resource:146	ACDP Mini ACDP APP version: 3.0.92 Company Introduction:	Resource version: 1
About		http://www.acdpmaster.com/	
http://www.autoemaster.com/en/index.asp http://www.acdpmaster.com/		http://www.autoemaster.com/en/index.asp	

2. There is a paster with authorization code on the module box, take off the green security seal and clean up the QR code.





3.Make sure the ACDP has bounded successfully, and click "me":

4. Click "module list":



5. Click "ADD"

🚛 中国移动 奈	16:23	🦉 🕑 🕇 51% 🔲
<	Module List	
Current device	ACDP-E7F73	
Device ID:A10E	B14B2B2979733D19C	B9216DF5F43
The following N	lodules have been autho	rized
Module ID:00	01	
Module name	e:Universal	
Authorization time:2018/5/11		
Local Licence	e:Exist	
Module ID:00	02	
Module name	e:Programmer-24/25/9	3/95 series
Authorization	time:2018/5/15	
Local Licence	e:Exist	
Module ID:A5	600	
Module name	BMW CAS1-CAS4 IMM	MO / ODO
Authorization	time:2019/10/29	
Local Licence	e:Exist	
Module ID:A5	ΰOA	
Module name	e:AntiTheft-BMW FEM/I	BDC key match
Authorization	time:2019/10/29	
AD	D	Refresh

6. Click "Scan QR Code" to start scanning the QR code on the paster or type the authorization card (Capital letters only)



7. Check the authorization card number and click "Submit" after confirmed.

📲 中国移动 奈	16:23	🦉 🕑 🕇 51% 🔲		
<	ADD	Submit		
authorization card				
1F7197D5				
	Scan QR Code			

8. When the prompt comes with authorization success, click "OK"

🛯 中国移动 🗢	16:24	🦉 🕑 🕇 51% 🔲
	ADD	Submit
authorization ca	rd	
1F7197D5		
	Scan QR Code	
	Prompt Authorization Success!	
	OK	

10. When the prompt comes with refreshing authorization info success, click "OK"

내 中国移动 🧟	? 16:	24	🖉 🕑 🕇 51% 🔲
	Modu	le List	
Current devi	ce:ACDP-E7F73		
Device ID:A1	0EB14B2B29797	33D19CB9216	DF5F43
The following	Modules have bee	en authorized	
Module ID:0001			
Module name:Universal			
Authorization time:2018/5/11			
Local Licence:Exist			
Module ID:	0002		
Module i Authoriz	Pro Refreshing authori	mpt zation info succe	255
Local Lic	0	ĸ	
Module ID:A500			
Module name:AntiTheft-BMW CAS4/CAS4+ non OBD key match			
Authorization time:2019/10/29			
Local Licence:Exist			
Module ID:A50A			
Module name:IMMO-BMW FEM/BDC key match			
Authorization time:2019/10/29			
	ADD	Ref	resh

11. If you want more module authorization info, please click "ADD" for more.

🔐 中国移动 穼	16:23	🖉 🕑 🕇 51% 💷	
<	Module List		
Current device:ACDP-E7F73			
Device ID:A10EB14B28	B2979733D19CB	9216DF5F43	
The following Modules I	have been authori.	zed	
Module ID:0001			
Module name:Univer	rsal		
Authorization time:2018/5/11			
Local Licence:Exist			
Module ID:0002			
Module name:Progra	ammer-24/25/93/	95 series	
Authorization time:20	018/5/15		
Local Licence:Exist			
Module ID:A500			
Module name:BMW CAS1-CAS4 IMMO / ODO			
Authorization time:2019/10/29			
Local Licence:Exist			
Module ID:A50A			
Module name:AntiTheft-BMW FEM/BDC key match			
Authorization time:20	019/10/29		
ADD		Refresh	

12. If you change another phone or PC, after the ACDP bounded, please click "Refresh" to download your authorization info.

🖬 中国移动 穼	16:23	😫 🕑 🕇 51% 🔲	
<	Module List		
Current device:ACD	P-E7F73		
Device ID:A10EB14B2B2979733D19CB9216DF5F43			
The following Modules have been authorized			
Module ID:0001			
Module name:Universal			
Authorization time:2018/5/11			
Local Licence:Exist			
Module ID:0002	Module ID:0002		
Module name:Programmer-24/25/93/95 series			
Authorization time:2018/5/15			
Local Licence:Exist			
Module ID:A500			
Module name:BMW CAS1-CAS4 IMMO / ODO			
Authorization time:2019/10/29			
Local Licence:Exist			
Module ID:A50A			
Module name:AntiTheft-BMW FEM/BDC key match			
Authorization time:2019/10/29			
ADD		Refresh	